

Fast delivery, reliable solutions.

During start-up of a new plant in South Africa, the customer had repeated problems with a mechanical seal that repeatedly failed. With start-up of the plant imminent, the customer required a reliable solution delivered quickly.

With only a 14 day emergency shutdown, AESSEAL® needed to work quickly to provide a suitable solution. AESSEAL® installed a CAPI SP dual mechanical seal, supplied within eight days of the request, coupled with the customer's existing API Plan 53C seal support system. The new solution operated reliably until the five-year shutdown, when it was routinely replaced.



'Meeting tight deadlines with reliable solutions'

Industry: Oil & Gas

Product: CAPI SP Dual Seal with API 53C Seal

Support system

Application: Hydrocarbon Recycle Pump

CH01448

MTBF Increase: 5900%

Reference N.O:

Savings: £340,000

