

AESSEAL® quality and service the key for Gulf company

A chemical company in the Gulf was looking to replace its existing pump single seal, which was continually leaking, and which they were having to replace about once a month. Typically, the replacement seal would begin to leak after just five to ten days.

The company turned to AESSEAL[®] for an alternative solution. AESSEAL[®] recommended replacing the faulty component with a 75mm B092SSU single spring enclosed bellows mechanical seal. This has proved to be a successful remedy, and the seal has been operating since July 2023 with no reports of leakage over seven months later.

The company has been impressed both by the success of the installation and the technical support and service which AESSEAL[®] has provided, and the confidence which it now has in AESSEAL's ability to deliver a quality product within a short period has led to further business.



'Reliability improved from <10 days to > 7 months'

Industry: Product: Application: MTBF Increase: Reference N.O: Chemical B092SSU Chemical Pump 2,180% (and counting) TD3100000



aesseal.com/info